

Hammer Inspection Report

HS/QS-10N

Manufacturing Date: 2025/4/28
Expiration date: N/A

Customer: ALESSA S.A.	Order no.: 25YF1B027	Lot number:25YF1B0271
Product Name: HAMMER	Type& Specification: HS-401G10	Inspection date: 2025-06-16
Order Quantity: 250 PCS	Inspection no.: 20PCS	

Inspection Items	Judgement Criterita	Inspection Results	Defective No.	Pass	Rejected
Appearance Inspection	Hammer head color conform to the requirements of the contract.	Eligible	0	pass	
	Appearance plating should be smooth, no bubbles, cracks.	Eligible	0	pass	
	LOGO printing is right and clear.	Eligible	0	pass	
Function Inspection	Hammer with handle should be solid can't loose, fall off.	Eligible	0	pass	
Parts Inspection	Conform to the requirements of the contract.	Eligible	0	pass	
Packaging and outer cartons Inspection	Middle box is in accordance with the contract requirements.	Eligible	0	pass	
	Product packaging is accordance with the contract requirements.	Eligible	0	pass	
	Carton marks are in accordance with contact requirements.	Eligible	0	pass	
	Side mark with information of packing size, gross net weight.	Eligible	0	pass	
Abnormity Condition	Critical defect	Major defect	Minor defect	Results Judgement:	
	None	None	None	Eligible	

Reviewed and proved by/Date: 2025-06-14 Inspected by/Date: 2025-06-16