

购物车出厂检验报告ROLLATOR TEST REPORT

广东凯洋医疗科技集团有限公司 GUANGDONG KAIYANG MEDICAL TECHNOLOGY GROUP CO., LTD.

品名 PRODUCT NAME	CAMINADOR	型号MODELOS	KY919L	订单号 LOT NO.	21W12- 113C	批量数 BATCH NUMBER	60	抽样数 INSPECTED QTY	60	检验标准	Q/KYYX4- 2006	
送检INSPECT	廖述龙 LIAO SHULONG	日期DATE	2022/7/12	检验员 INSPECTOR	张成贤 ZHANG	日期 DATE MANUFACTURING	2022/7/12	审核 AUDITING	2022/7/12	日期DATE	2022/7/12	
No.	Test points	Test details						Test result	Evaluation			
1	Outlook	1) The whole surface should be smooth without burrs and sharp edges. A cap shall be attached at the end of the tube.						Conformity	Pass			
		2) The parts with POWDER COATED/ CHROMED plated shall not contain obvious defection such as drops or burrs,etc..						Conformity	Pass			
		3) The surface of the welding joint of the parts shall be smooth, without obvious defection such as drops or burrs etc..						Conformity	Pass			
2	Function and Assemble	4)All the spare parts shall only be assembled upon the inspection . The assembly of the spare parts shall be in the due way. All the spart parts shall fit in the product closely.No loose part is accetable.						Conformity	Pass			
		5) All the removable parts shall be easy to remove and easy to fix the position. The detachable parts shall be easy to detached.						Conformity	Pass			
3	Size							Conformity	Pass			
		6) Every size is same as the request .										
								Conformity	Pass			
		7)Adjust the nult to fit each hole .										
4	Packing and Carton	8)It must same as the customer's request .						Conformity	Pass			
5	Comment	The item being tested conforms to all the requirements of GB/T 14728-93.										